1/11 SYSTEM AND METHOD FOR AUTOMATED FRINGE COUNTING USING IMAGE INFORMATION HUSTON ET AL. B02962-00042







FIG. 1


2/11 SYSTEM AND METHOD FOR AUTOMATED FRINGE COUNTING USING IMAGE INFORMATION HUSTON ET AL. B02962-00042

FIG.2











6/11
SYSTEM AND METHOD FOR AUTOMATED
FRINGE COUNTING USING IMAGE INFORMATION
HUSTON ET AL.
B02962-00042





F1G.4

891

7/11
SYSTEM AND METHOD FOR AUTOMATED
FRINGE COUNTING USING IMAGE INFORMATION
HUSTON ET AL.
B02962-00042







10/11
SYSTEM AND METHOD FOR AUTOMATED
FRINGE COUNTING USING IMAGE INFORMATION
HUSTON ET AL.
B02962-00042
FROM FI FROM FIG.6-2 FIG.6-3 338 414 DETERMINE AVG. **BRIGHTNESS** STOP DATA AT EACH SELECTED CAPTURE & CONTROL SAMPLING REGION FOR 410 EACH IMAGE CAPTURED 346 NOTIFY USER IN PAUSE MODE PLOT AVG. BRIGHTNESS ON AVG. BRIGHTNESS YES V. TIME OR PRESSURE 406 **CURVE** 342 "PAUSE" BUTTON CONTROL **SELECTED PRESSURIZATION** SYSTEM BASED UPON CONTROL NO **PARAMETERS** 362 *(350)* "STOP" YES MAX. BUTTON YES OR MIN. SELECTED OCCURED DISPLAY *-354* MAX/MIN NO **INDICATOR** c358 **MAXIMUM** NO **PRESSURE REACHED** YES TO FIG.6-4

11/11 SYSTEM AND METHOD FOR AUTOMATED FRINGE COUNTING USING IMAGE INFORMATION HUSTON ET AL. B02962-00042 FROM FIG FROM FIG.6-3 446 c 422 **EACH** YES CALCULATE MATERIAL **BRIGHTNESS CURVE PROPERTIES** ACCEPTABLE 450 **USER SELECTS** NO "DISPLAY" BUTTON - 426 454 NO "MANUAL CHECK" OPEN NEW WINDOW **SELECTED** AND DISPLAY PRESS. V. DISPLACEMENT 430 DIAGRAM AND YES MATERIAL PROPERTIES ALLOW USER TO MOVE AND/OR ADD 458-ONE OR MORE RUN YES NEW **INDICATORS TEST** NO

